

**From:** [Garyg Miller](#)  
**To:** [Barbara Nann](#); [Dipanjana Bhattacharya](#); [Kevin Shade](#); [Susan Roddy](#)  
**Subject:** Fw: From Don Williams: Need Removal Assistance  
**Date:** 06/08/2010 10:47 AM

---

Gary Miller, P.E.  
Remediation Project Manager  
EPA Region 6 - Superfund (6SF-RA)  
(214) 665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)

----- Forwarded by Garyg Miller/R6/USEPA/US on 06/08/2010 10:47 AM -----

**From:** <d1cnv@tx.rr.com>  
**To:** Mark Hansen/R6/USEPA/US@EPA, Susan Webster/R6/USEPA/US@EPA, Garyg Miller/R6/USEPA/US@EPA, Michael Hebert/R6/USEPA/US@EPA  
**Cc:** Charles Faultry/R6/USEPA/US@EPA, Carlos Sanchez/R6/USEPA/US@EPA  
**Date:** 06/07/2010 01:17 PM  
**Subject:** From Don Williams: Need Removal Assistance

---

Mark/Susan,

I am requesting the assistance of the removal program at a couple of remedial sites, Oklahoma Refining and Gulfco. At Oklahoma Refining, we need a little bit of followup work done on a drainage ditch in the area here the refinery equipment used to be located. This equipment was dismantled several years ago by EPA. The drainage ditch through the site now has a high spot the prevents water from draining away from the town of Cyril, resulting in periodic flooding in an area of twon adjacent to the refinery. Mike Hebert thinks it would take a day to repair the drainage ditch at a cost of less than \$50K. Is there any way that the removal branch can assist us in fixing the drainage problem at ORC?

At Gulfco, the PRPs ave expressed a willingness to undertake a couple removal actions to address process equipment, cap repair, and wetlands hot spot mitigation. The remedial project team wants to take th approach of addressing the process equipment as a time critical removal and addressing the cap repair and hot spots as a non-time critical removal. We need to borrow an OSC for a day trip with the RPM to Gulfco to inspect the site for an imminenet and substantial endangerment determination.

We would like to undertake these activities as quickly as possible. I am in Albuquerque at the uranium meetings all week. If you need additional information, please talk to Charles, Carlos, Gary, or Mike.

Thank you for your assistance.